

JIMMY PARK - 1 CO - OP. HSG. SOC. LTD.

Regd. No. NBOM/CIDCO/HSG/(OH)/717/JTR/98-99 DT. 13.01.1999

PLOT NO. 182 D, SECTOR - 17, NERUL, NAVI MUMBAI - 400 706.

Email id. jp1society@gmail.com

Date: - 22/06/2022

Dear Members,


This is to inform you the we have just received the Structural Audit Report from NMMC (attached herewith for reference) which is self-explanatory.

As per the report, our society, Jimmy Park-1 is **not at all safe** (Page no.23 point no.06 of audit report reference no. YECPL/SA/Nerul2022-01 Date-20/06/2022- "It will be prudent to Demolish these Buildings") to reside in & informed all the members (42 members) of the society to **vacate** their premises with **immediate effect**. Not a single family should reside herein even for a day.

We have requested the NMMC officials to allow us to take out our belongings which they have agreed to on humanitarian ground but, for a FEW DAYS only.

Once again it is our earnest request to each & every member of the society to vacate their respective premises **IMMEDIATELY** if not DONE yet.

Regards,


(Chairman / Secretary / Treasurer)